



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	FR/LCI/QAR06.0005/13	Page 1 of 2
QAR Free Ref. No.:	159456-732269	Status: Issued
Details of change:	Renewal audit	Date of issue: 2022-04-07
Site(s) audited:	EXHEAT Industrial Limited Threxton House Threxton Road Industrial Estate Watton - Thetford - Norfolk IP25 6NG United Kingdom EXHEAT Limited Threxton Road Industrial Estate Watton - Thetford - Norfolk IP25 6NG United Kingdom	Valid until: 2025-02-11 Audit date: 2022-01-27
Issuing ExCB:	LCIE - Laboratoire Central des Industries Electriques (LCIE)	
Manufacturer:	EXHEAT Limited Threxton Road Industrial Estate Watton - Thetford - Norfolk IP25 6NG	
Location of Manufacturer:	United Kingdom	
Product information:	Hazardous area process heat and control solutions	
Protection concept:	Gb : Ex d, Ex e, Ex mb, Ex h Db : Ex tb, Ex mb, Ex h	
Related QARs:		
FR/LCI/QAR06.0005/00	FR/LCI/QAR06.0005/01	FR/LCI/QAR06.0005/02
FR/LCI/QAR06.0005/03	FR/LCI/QAR06.0005/04	FR/LCI/QAR06.0005/05
FR/LCI/QAR06.0005/06	FR/LCI/QAR06.0005/07	FR/LCI/QAR06.0005/08
FR/LCI/QAR06.0005/09	FR/LCI/QAR06.0005/10	FR/LCI/QAR06.0005/11
FR/LCI/QAR06.0005/12		

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for
previous versions:

[IECEX CML 20.0132X issue: 0](#)
[IECEX ITS 17.0025X issue: 0](#)
[IECEX ITS 19.0024X issue: 0](#)
[IECEX LCI 06.0005X issue: 2](#)
[IECEX LCI 06.0006X issue: 3](#)
[IECEX LCI 06.0006X issue: 6](#)
[IECEX LCI 07.0004X issue: 0](#)
[IECEX LCI 07.0005X issue: 0](#)
[IECEX LCI 07.0009X issue: 0](#)
[IECEX LCIE 12.0030X issue: 0](#)
[IECEX SIR 17.0082X issue: 1](#)
[IECEX ULD 16.0002X issue: 1](#)
[IECEX ULD 17.0004 issue: 0](#)

[IECEX ITS 17.0012X issue: 0](#)
[IECEX ITS 18.0040X issue: 0](#)
[IECEX LCI 06.0005X issue: 0](#)
[IECEX LCI 06.0006X issue: 1](#)
[IECEX LCI 06.0006X issue: 4](#)
[IECEX LCI 07.0003X issue: 0](#)
[IECEX LCI 07.0004X issue: 1](#)
[IECEX LCI 07.0005X issue: 1](#)
[IECEX LCI 08.0025X issue: 0](#)
[IECEX LCIE 15.0069U issue: 0](#)
[IECEX SIR 18.0053X issue: 0](#)
[IECEX ULD 16.0002X issue: 2](#)

[IECEX ITS 17.0012X issue: 1](#)
[IECEX ITS 18.0040X issue: 1](#)
[IECEX LCI 06.0005X issue: 1](#)
[IECEX LCI 06.0006X issue: 2](#)
[IECEX LCI 06.0006X issue: 5](#)
[IECEX LCI 07.0003X issue: 1](#)
[IECEX LCI 07.0004X issue: 2](#)
[IECEX LCI 07.0005X issue: 2](#)
[IECEX LCI 12.0008X issue: 0](#)
[IECEX SIR 17.0082X issue: 0](#)
[IECEX ULD 16.0002X issue: 0](#)
[IECEX ULD 16.0002X issue: 3](#)



IECEX Quality Assessment Report Summary

QAR Ref. No.: **FR/LCI/QAR06.0005/13**

Page 2 of 2

Comments: Quality Assurance Notification under directive 2014/34/UE : LCIE 02 ATEX Q 8015